



**US Army Corps
of Engineers**
Philadelphia District

**Southeastern Pennsylvania Environmental
Assistance Program**
(Section 566 of Water Resources Development Act of 1996)

**Wissinoming Sinking Homes Study
Philadelphia, PA**

Prepared By

**U.S. ARMY CORPS OF ENGINEERS
PHILADELPHIA DISTRICT**

MAY 2000

***** NOTICE *****

This document is an INFORMATIONAL REPORT issued to the client, the Philadelphia Federal Congressional Delegation, only. Use of this report by other parties for any reason is prohibited except for general informational purposes. Other usage will be considered beyond the scope of the study and will discharge the U.S. Army Corps of Engineers, Philadelphia District of any responsibility whatsoever for any such reliance on this report or occurrence of any conditions not identified in this report.

This report is limited in the scope of the study and/or investigation as contained in report, and is rendered on an “opinion” basis. Latent or concealed defects, which cannot reasonably be discovered without the use of Engineering practices beyond those contained in the Scope of Study and/or Description of Work, may not be identified.

While every reasonable effort and good engineering practices subject to the limitation of funding were used to ascertain the present condition of the inspected areas, the U.S. Army Corps of Engineers, Philadelphia District does not make any representation, guarantee, or warranty as to the reported condition or any property’s future condition.

TABLE OF CONTENTS

<u>Section</u>	<u>Page</u>
1.0 Executive Summary.....	1
2.0 Description/Background of Project.....	5
2.1 Study Area.....	5
2.2 Scope of Study/Investigation.....	6
3.0 Topographical Change Maps.....	8
3.1 US Army Corps of Engineers, Philadelphia District Map.....	8
3.1.1 Description of Work.....	8
4.0 Subsurface Investigation.....	9
4.1 Geotechnical and Geophysical Investigations.....	9
4.1.1 Tantala Associates Study	9
4.1.2 Tantala Associates Geotechnical Investigation.....	9
4.1.3 US Army Corps of Engineers Geophysical Investigation.....	10
4.2 Subsurface Conditions.....	13
4.2.1 Geological Setting.....	13
4.2.2 Existing Subsurface Profile.....	13
4.2.3 Groundwater.....	14
5.0 Building Exterior Assessments.....	16
5.1 General.....	16
5.2 Limits of Assessment.....	16
5.3 Description of Structures.....	16
5.4 Assessment Criteria.....	17
5.5 Assessment Results.....	17
6.0 Infrastructure.....	19
6.1 Existing Infrastructure.....	19
6.1.1 General.....	19
6.1.2 Water Lines.....	19
6.1.3 Gas Lines.....	19
6.1.4 Sewer lines.....	20
6.2 Infrastructure Observations.....	20
6.2.1 Laterals.....	20
6.2.2 Sewers.....	22

<u>Section</u>	<u>Page</u>
7.0 Conclusions.....	23
7.1 US Army Corps of Engineers, Topographical Change Map.....	23
7.2 Subsurface Investigation.....	23
7.2.1 Geotechnical Investigation.....	23
7.2.2 Geophysical Investigation.....	25
7.1 Building Exterior Assessments.....	26
7.2 Infrastructure.....	26
7.4.1 Laterals.....	26
7.4.2 Sewers.....	27
8.0 Recommendations	28
8.1 Topographical Change Maps.....	28
8.2 Subsurface Investigation.....	28
8.3 Building Exterior Assessments.....	29
8.4 Infrastructure.....	29
9.0 Bibliography	30
10.0 Appendix.....	31
A USACE Topographical Change Map	
B Geophysical Investigation	
C Building Exterior Assessment	
D Sewer/Lateral Investigation	
E Southeastern Pennsylvania Environmental Assistance Program, Section 566 of the Water Resources Development Act (WRDA) of 1996	